

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-002	Smoke	8/6/2008	ADS/TM	S07AA1001MH	Dry	Yes	1,406.49



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-002	Smoke	8/6/2008	ADS/TM	S07AA1001MH	Dry	Yes	1,406.49

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S07YY_014G1	S07YY_014MH	S07YY_009MH	320.0167	8
S07YY_009G1	S07YY_009MH	S07YY_001MH	336.1523	8
S07AA1016G1	S07AA1016DE	S07YY_009MH	750.3230	8

Observations & Photos

Obs_ID S1028-002-OB01

Address 3605 Callaway Ave.

Status Private

Source Cleanout

Location Yard - front

Nearest MH S07AA1001MH

Comments Smoke from cleanout in front yard. 3605 Callaway Ave.



Picture \S1028-002-OB01-P01.jpg

Comments Front of house, 3605 Callaway Ave.